Owner Name and Address: Ezzies Wholesale Inc PO Box 1770 Malta MT 59538 Phone: (406) 654-2331

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0307801	Ezzies Wholesale Inc Chinook	US Highway 2 E	Chinook	59523	

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/CP
1 / S1	873 5/6/1976	Gasoline	Asphalt Coated or Bare Steel	Flexible Plastic	Pressurized	ABCDEFGHIJ®L	Yes
Currently in Use	30 / Yes	15,000	None	Double-Walled		B DEF•HIJ®L	Yes Yes Yes
2 / S2	874 5/6/1976	Diesel	Asphalt Coated or Bare Steel	Flexible Plastic	Pressurized	ABCDEFGH1J&L	Yes
Currently in Use	30 / Yes	15,000	None	Double-Walled		B DEF•H1J&L	Yes Yes Yes
3 / S3	875 5/6/1976	Diesel	Asphalt Coated or Bare Steel	Flexible Plastic	Pressurized	(ABCDEFGH)J®U	Yes
Currently in Use	30 / Yes	12,000	None	Double-Walled		(B DEF®H)J%U	Yes Yes Yes
4 / S4	876 5/6/1976	Gasoline	Asphalt Coated or Bare Steel	Flexible Plastic	Pressurized	(ABCDEFGH)J®L	Yes
Currently in Use	30 / Yes	12,000	None	Double-Walled		(B DEF®H)J%L	Yes Yes Yes
5 / S5 Currently in Use	877 5/6/1976 30 / Yes	Diesel 12,000	Asphalt Coated or Bare Steel None	Flexible Plastic Double-Walled	Pressurized	(ABCDEFGH)J.L B DEF.H)J.KL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
0308688	Town Pump Inc Chinook Food Store	US Highway 2 W	 Chinook	59523	(406) 357-2365	

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
1 / 08 Currently in Use	2384	1/1/1993 13 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
2 / 09 Currently in Use	2385	1/1/1993 13 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABC●EFGHIJ&L ● ●EFGHIJ&L</pre>	Yes Yes Yes Yes
3 / 07 Currently in Use	4462	1/1/1993 13 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
4 / 06 Currently in Use	2382	1/1/1993 13 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
10 / 10 Currently In Use	4354	6/1/2001 05 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKL B OEFOHIJKL	Yes Yes Yes Yes
11 / 11 Currently In Use	4355	6/1/2001 05 / No	5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKL B OEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 2 of 9

Owner Name and Address: Farmers Union Oil Co Chinook PO Box 339 Chinook MT 59523 Phone: (406) 357-2280

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0310274	Farmers Union Oil Co Chinook	135 1st St	Chinook	59523	_

TankID/Alt TankID Status	- l	nstalled Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
1 / 11 Currently in Use	962 4/1/	/1995 11 / No	Gasohol 10,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	B DEF H 1 J K L	Yes Yes Yes Yes
2 / 12 Currently in Use		/1995 11 / No	Gasoline 10,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKU B DEFOHIJKU	Yes Yes Yes Yes
3 / 13 Currently in Use		/1995 11 / No	Gasoline 20,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	B DEFOHIJKU	Yes Yes Yes Yes
4 / 14 Currently in Use	965 4/1/	/1995 11 / No	Diesel 12,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOHIJKL B DEFOHIJKL	Yes Yes Yes Yes
5 / 15 Currently in Use	966 4/1/	/1995 11 / No	Diesel 12,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOHIJK) B DEFOHIJK)	Yes Yes Yes Yes
6 / 16 Currently in Use		/1995 11 / No	Diesel 12,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABC • E F • H 1 J K L B D E F • H 1 J K L	Yes Yes Yes Yes
17 / 17 Currently in Use	968 4/1/	/1995 11 / No	Diesel 12,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOHIJKL B (DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 3 of 9

Owner Name and Address: E Z Mart PO Box 249 Harlem MT 59526 Phone: (406) 353-2335

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0305982	E Z Mart	US Highway 2	Harlem	59526	(406) 353-2411

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/CP
4 / 04 Currently in Use	3265	8/1/1993 12 / No	Gasohol 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABC • E F G H J K L	Yes Yes Yes Yes
5 / 05 Currently in Use	3266	8/1/1993 12 / No	Gasohol 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGH))(KL) (O) (E) (F) (H) (J) (K)	Yes Yes Yes Yes
6 / 06 Currently in Use	3267	8/1/1993 12 / No	Gasohol 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGH))(C) (O) (E) (F) (H) (F) (C)	Yes Yes Yes Yes
7 / 07 Currently in Use	3268	8/1/1993 12 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABCOEFGHJ&L</pre>	Yes Yes Yes Yes
8 / 08 Currently in Use	3269	8/1/1993 12 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	ABCOEFGHUJ&L • • • • • • • • • • • • • • • • • • •	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 4 of 9

Owner Name and Address: Fort Belknap Development Corp RR 1 Box 66 Harlem MT 59526 Phone: (406) 353-2205

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0309729	Fort Belknap Kwik Stop	US Highway 2 & MT Highway 66	Harlem	59526	(406) 353-2205

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
1 / 01 Currently in Use	3820	8/2/1988 17 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJKL (D) (D) (B) (D) (D) (D) (D) (D) (D) (D) (D) (D) (D	No Yes Yes Yes
2 / 02 Currently in Use	3821	8/2/1988 17 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJKU (O) (E) (F) (H) (J) (K) (L)	No Yes Yes Yes
3 / 03 Currently in Use	3822	8/2/1988 17 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABC) EFGHIJKU	No Yes Yes Yes
4 / 04 Currently in Use	3823	8/2/1988 17 / No	Diesel 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABC) EFGHIJKL (D) (D) EFGHIJKL	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 5 of 9

Owner Name and Address: Harley & Caroline Brown PO Box 578 Harlem MT 59526 Phone: (406) 353-4672

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0307987	Valley Grocery 2	US Highway 66	Hays	59527	(406) 353-2851

TankID/Alt TankID	Tag Installed Number Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/CP
1 / 01 Currently in Use	5/8/1976 30 / No	Gasoline 6,000	Asphalt Coated or Bare Steel None	Galvanized Steel None	Not Listed	ABCDEFGHIJKO B DEFGHIJKO	No No No No
2 / 02 Currently in Use	5/8/1976 30 / No	Gasoline 4,000	Asphalt Coated or Bare Steel None	Galvanized Steel None	Not Listed	ABCDEFGHIJKO B DEFGHIJKO	No No No No
3 / 03 Currently in Use	5/8/1976 30 / No	Gasoline 4,000	Asphalt Coated or Bare Steel None	Galvanized Steel None	Not Listed	ABCDEFGHIJKO B DEFGHIJKO	No No No No
4 / 04 Currently in Use	5/8/1976 30 / No	Gasoline 4,000	Asphalt Coated or Bare Steel None	Galvanized Steel None	Not Listed	(ABCDEFGHIJK) (B DEFGHIJK)	No No No No
5 / 05 Currently in Use	5/8/1976 30 / No	Diesel 4,000	Asphalt Coated or Bare Steel None	Galvanized Steel None	Not Listed	(ABCDEFGHIJK) (B DEFGHIJK)	No No No No
6 / 06 Currently in Use	5/8/1976 30 / No	Diesel 2,000	Asphalt Coated or Bare Steel None	Galvanized Steel None	Not Listed	(ABCDEFGHIJK) (B DEFGHIJK)	No No No No

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006

Owner Name and Address: Hays Lodgepole School Dist 50 PO Box 110 Hays MT 59527 Phone: (406) 673-3120

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0311577	Hays Lodge Pole High School	MT Highway 66	Hays	59527	(406) 673-3120

TankID/Alt TankID Status	Tag Installed Number Age/AS1	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
3 / S3 Currently In Use	4616 4/1/1998 08 / N	Heating Oil 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKU B DEFOHIJKU	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	Not Listed

Report Generation Date: 7/3/2006 Page 7 of 9

Owner Name and Address: Hays Lodgepole School Dist 50 PO Box 110 Hays MT 59527 Phone: (406) 673-3120

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0311578	Hays Lodge Pole School Dist 50	MT Highway 66 & Route 8	Hays	59527	(406) 673-3220

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/CP
4 / S4 Temporarily Out of U		8/1/1999 06 / Yes	Heating Oil 2,500	Concrete None	Flexible Plastic Double-Walled	U.S. Suction	8 DEF 0 H 1 J K L	Yes Yes Yes Yes
5 / S5 Temporarily Out of U		8/1/1999 06 / Yes	Heating Oil 2,500	Concrete None	Flexible Plastic Double-Walled	U.S. Suction	ABCDEFGH1J&L B DEF@H1JKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 8 of 9

Owner Name and Address: Farmers Union Oil Co Chinook PO Box 339 Chinook MT 59523 Phone: (406) 357-2280

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613805	Farmers Union Oil Co Turner	US Highway 241	 Turner	59542	(406) 357-2280

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
1 / S1 Currently In Use	969 8/14/1997 08 / Yes	Gasoline 10,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	ABCDEFGHIOKL B DEFOHIJKL	Yes Yes Yes Yes
2 / S2	970 8/14/1997	Diesel	Unknown	Flexible Plastic	Pressurized	ABCDEFGH()•KL	Yes
Currently In Use	08 / Yes	10,000	None	Double-Walled		B DEF•H(),KL	Yes Yes Yes
3 / S3	971 8/14/1997	Gasoline	Unknown	Flexible Plastic	Pressurized	ABCDEFGH10KL	Yes
Currently In Use	08 / Yes	10,000	None	Double-Walled		B DEF0H10KL	Yes Yes Yes
4 / S4	972 8/14/1997	Diesel	Unknown	Flexible Plastic	Pressurized	(ABCDEFGH10KL	Yes
Currently In Use	08 / Yes	6,000	None	Double-Walled		B DEFOH10KL	Yes Yes Yes
5 / S5 Currently In Use	3606 8/14/1997 08 / Yes	Diesel 6,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	(ABCDEFGHIJEL) (B DEFOHIJEL)	Yes Yes Yes Yes
6 / S6	3607 8/14/1997	Diesel	Unknown	Flexible Plastic	Pressurized	ABCDEFGH1J&L	Yes
Currently In Use	08 / Yes	6,000	None	Double-Walled		B DEF•H1JKL	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006